Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No. LC 032233 (a)

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

6. If Indian, Allottee or Tribe Name

Use "APPLICATION FOR PERMIT—" for such	proposals	
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation N. HOBBS (G/SA) UNIT Sec. 2	
1. Type of Well    X Oil   Gas   Other   2. Name of Operator   Shell Western E & P Inc.   3. Address and Telephone No.   P.O. Box 576 Houston, TX 77001-0576   4. Location of Well (Footage, Sec., T., R., M., or Survey Description)   UNIT LTR L, 2310° FSL & 990° FWL   SEC. 29, T18S - R38E	8. Well Name and No. NHU-29-131  9. API Well No. 30-025-07447  10. Field and Pool, or Exploratory Area HOBBS (G/SA)  11. County or Parish, State	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NA	TURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Abando	Onmen! Change of Plans  Pletion New Construction	
Casing  Final Abandonment Notice  Alterin	ng Back Repair Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

POH W/PROD EQUIP. CO TO 4116'. SET RBP @ 4000'. PT CSG & LNR ABV RBP TO 500#. REL RBP & RESET @ 4070'. SET PKR DIRECTLY ABV RBP & PT TO 500#, HELD. REL PKR & PU TO 4015'. ESTAB INJ RT. REL PKR & RBP, POH. SET CIBP @ 4072'. SET CICR @ 3987'. SQZD PERFS 4050-58' W/100 SX CLS C CMT + 350 SCFPB N2 FOLLOWED BY 50 SX CLS C CMT + 2% CACL2. DID NOT OBTAIN SQZ. SI OVERNITE. COULD NOT PMP THRU CICR. STINGER PLUGGED. CHNG OUT STINGER. TAG TOP OF CICR @ 3987'. CIRC'D HOLE CLN. STING INTO CICR. ATTMPTD TO ESTAB INJ RT. COULD NOT PMP INTO CICR. STINGER PLUGGED. UNPLUG & STUNG INTO CICR. COULD NOT PMP INTO CICR. DRLD UP CICR, PUSHED REMNANTS TO TOP OF CIBP @ 4072'. ESTAB INJ RT. RIH W/OE TBG TO 4071'. SPOTTED 25 SX CLS C CMT + .4 OF 1% CFR-2 (PREM +) CMT. PU TO 3889'. REVERSE CIRC UNTIL HOLE CLN. COULD NOT PMP INTO PERFS. TAG TOC @ 3886'. DRLD THRU CMT & CIBP @ 4072' TO 4095'. DRLD UP CIBP & PUSHED REMNANTS TO TOP OF CIBP @ 4130'. PERF'D SA 4097' - 4120' (2 JSPF). ATTMPTD TO BREAKDOWN PERFS @ 4097' W/9 BBLS 15% NEFE HCL. NO BREAKDOWN. REVERSED OUT ACID. REPERF'D SA 4097' - 4120' (2 JSPF). SPOT 250 GALS 15% NEFE HCL. COULD NOT BREAKDOWN PERFS. REPERF'D 4080-90' (2 JSPF). SPOT 250 GALS 15% NEFE HCL. ACD PERFS 4080' - 4120' Acc W/1000 GALS 15% NEFE HCL. INST PROD EQUIP & RETD TO PROD.

the bush foresine is the and correct		
14. I hereby certify that the foregoing is true and correct Signed Fruttle wide J. H. SMITHERMAN	Title REGULATORY SUPV.	Date 6/27/91
(This space for Federal or State office use)  Approved by Conditions of approval, if any:	Title	Date
	anney of the United States	any false fictitious or fraudulent statements