- Al Maria Andre Alexandra - P. Maria Andre Alexandra - MODria, Matter Alexandra (198**240** 

Form 9-331 Form Approved. Dec. 1973 Budget Bureau No. 42-R1424 UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR LC 032233 (a) **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) N. HOBBS (G/SA) UNIT 8. FARM OR LEASE NAME 1. oil SECTION 29 gas well KX well other 9. WELL NO. 2. NAME OF OPERATOR 141 SHELL WESTERN E&P INC. 10. FIELD OR WILDCAT NAME, 3. ADDRESS OF OPERATOR . HOBBS (G/SA) P. O. BOX 991, HOUSTON, TEXAS 77001 11. SEC., T., R., M., OR BLK. AND SURVEY OR 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AREA below.) <u>SECTION 29,</u> T-18-S, R-38-E AT SURFACE: UNIT LTR M, 330' FSL & 330' FWL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: SAME щ., с LEA AT TOTAL DEPTH: SAME NM ÷.... 14. API NO. ÷.: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, N/A REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3644' GR 🐨 👘 . • **REQUEST FOR APPROVAL TO:** SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF  $\square$ L FRACTURE TREAT SHOOT OR ACIDIZE ē. REPAIR WELL (NOTE: Report results of multiple completion or zone PULL OR ALTER CASING Γ change on Form 9-330.) MULTIPLE COMPLETE Π CHANGE ZONES m. CH H 0 ABANDON\* (other) DEEPEN IVED 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* **n** Plug back with 20/40 sand from PBTD (4130'+ to 4108'+. 1. Set 5-1/2" cement retainer @ 3900'+. Squeeze the Grayburg and San 2. Andres Zone I (3960' - 4108'+ with 1500 gals Flochek and 75 sx Class "C" 50/50 poz mix cement with 2% CaCl2. Wait on cement 24 hours. Drill out cement retainer and cement to 4092'+. 3. 4. Clean out sand, Calseal and hydromite to  $4218^{-1}$ . 5. Deepen well to 4258'. 6. Run GR/CNL log from TD (4258') to 2258'. Perforate open hole based on CNL log interpretation. 7. Acidize open hole w/13,860 gals (330 bbls) 15% HCl-NEA. 8. 9. Install production equipment and return well to production. Subsurface Safety Valve: Manu. and Type \_ Set @ Ft. 18. I hereby certify that the foregoing is true and correct SUPERVISOR I. FORE TITLE REG. & PERMITS DATE January 17, 1984 SIGNER (This space for Federal or State office use) APPROVED BY . W. CHESTER TITLE CONDITIONS OF APPROVAL IF ANY: MAR 2 198-1 DATE \*See Instructions on Reverse Side

