

TAPE
 le
 S.C.S.
 W.D. OFFICE
 CRATOR

3a. Indicate Type of Lease
 State ☐ Fee ☐
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☐ GAS WELL ☐ OTHER ☐
 Name of Operator
 Shell Oil Company
 Address of Operator
 P.O. Box 991 Houston, TX 77001
 Location of Well
 UNIT LETTER H 1650 FEET FROM THE north LINE AND 990 FEET FROM
 THE east LINE, SECTION 29 TOWNSHIP 18S RANGE 38E N.M.P.M.

7. Unit Agreement Name
 8. Form or Lease Name
 Grimes
 9. Well No.
 5
 10. Field and Pool, or Willcat
 Hobbs(G/SA)

15. Elevation (Show whether DF, RT, GR, etc.)
 3647' GL

12. County
 Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
 REPAIR REMEDIAL WORK ☐
 PERMANENTLY ABANDON ☐
 RE-ENTER AND REPLUG ☐
 AMENDED
 CHANGE PLANS ☐
 PLUG AND ABANDON ☐

SUBSEQUENT REPORT OF:
 REMEDIAL WORK ☐
 COMMENCE DRILLING OPERATIONS ☐
 CASING TEST AND CEMENT JOBS ☐
 ALTERING CASING ☐
 PLUG AND ABANDONMENT ☐

Describe the Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Dig out cellar. Remove marker. Rig up PU and reverse circulator.
2. Drill out surface cmt plug in 12 1/2" csg. Clean out to 3930'.
3. Spot 100' Class "C" cmt plugs @3930'-3830'; 1685'-1585'; 1072'-972'.
4. Spot Class "C" cmt plug from 400'-175'. Spot 10 ft. cmt. plug at surface.
5. Weld plate over 12 1/2" csg. Install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

A.J. Fore
 TITLE Supervisor Regulatory & Permits
 DATE January 30, 1981

APPROVED BY
 CONDITIONS OF APPROVAL, IF ANY: