Submit 3 Copies to Appropria : District Office	State of New Me Energy, Minerals and Natural Re		Form C-103 Revised 1-1-89	
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240			WELL API NO.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico		5. Indicate Type of Lease STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVED (FORM C) 1. Type of Well:	ICES AND REPORTS ON WEL OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PEI -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 30	
MET X MET OYS	OTHER			
2. Name of Operator Sholl Woodown FSD Inc.			8. Well No.	
Shell Western E&P Inc. 3. Address of Operator	(war 45B	7	121	
P.O. Box 576 Houston, TX	(77001-0576	シ	9. Pool name or Wildcat HOBBS (G/SA)	
Unit Letter <u>E</u> : 23	Township 18S Ra 10. Elevation (Show whether 3662' DF	unge 38E	330 Feet From The WEST Line NMPM LEA County	
11. Check	Appropriate Box to Indicate 1	Nature of Notice R	enort or Other Data	
NOTICE OF IN	TENTION TO:		SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND CE		
OTHER: OAP & AT	X	OTHER:		
12. Describe Proposed or Completed Opera work) SEE RULE 1103.	ntions (Clearly state all pertinent details, ar	nd give pertinent dates, inclu	ding estimated date of starting any proposed	
1. POH W/PROD EQMT. 2. CO TO 4288' (PBTD). 3. PERF SA 4042-48' (2 SPF 4. AT PERFS 4042' - 4283' 5. INST PROD EQMT & RTP.	.). W/1172 GAL 15% NEFE HCL.			

SIGNATURE COMPANY	of my knowledge and belief. TITLE TECH, MANAGER - ENVIR, ENG	DATE6/0	3/92	
TYPE OR PRINT NAME W. F. N. KELLDORF		DATE	, 713/870-342	
(This space for State Use)				
(Ind space to one only				