

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

CIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT

8. From or Lease Name
Section 30

Name of Operator
SHELL WESTERN E&P INC. (4431 WCK)

Address of Operator
P. O. BOX 576, HOUSTON, TEXAS 77001

9. Well No.
121

Location of Well
UNIT LETTER E 2310 FEET FROM THE North LINE AND 330 FEET FROM
THE West LINE, SECTION 30 TOWNSHIP 18-S RANGE 38-E N.M.P.M.

10. Field and Pool, or Wildcat
HOBBS (G/SA)

15. Elevation (Show whether DF, RT, GR, etc.)
3662' DF

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PLUG OR ALTER CASING ☐	OTHER OAP, AT ☒	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) POOH w/ prod equip.
- 2) CO to CIBP @ 4110'.
- 3) Perf San Andres 4051' - 4070' w/ 2JSPF.
- 4) AT San Andres 4051' - 4070' w/ 1200 gals 15% HCl using pkr.
- 5) RIH w/ prod equip and return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE JAN 9 1989

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

JAN 16 1989