

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-07466 ✓
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name H.D. MCKINLEY
8. Well No. 6
9. Pool name or Wildcat BOWERS SEVEN RIVERS
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3664' DF

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER TA'D	2. Name of Operator AMERADA HESS CORPORATION
3. Address of Operator DRAWER D, MONUMENT, NM 88265	4. Well Location Unit Letter C : 660 Feet From The NORTH Line and 1909 Feet From The WEST Line Section 30 Township 18S Range 38E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3664' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-17-93

MIRU POOL WELL SER. PU. & WELL PLUGGING EQUIPMENT & KILLED WELL W/40 BBLS. 10# BRINE WATER. INSTALLED BOP & TOH W/TBG. TIH W/A ELDER 5-1/2" CIBP & SETTING TOOL & ATTEMPTED TO SET CIBP AT 3100' W/NO RESULTS. TOH W/TBG. & TOOLS. TIH W/A ELDER 5-1/2" CIBP & SETTING TOOL & SET CIBP AT 3100'. DISPLACED HOLE W/70 BBLS. 9.5# MUD. SPOTTED 25 SKS. CEMENT PLUG FROM 3100' TO 2850'. PULLED & LAID DOWN 40 JTS. 2-3/8" TBG. SPOTTED A 25 SK. CEMENT PLUG FROM 3100' TO 2850'. PULLED & LAID DOWN 40 JTS. 2-3/8" TBG. SPOTTED A 25 SK. CEMENT PLUG FROM 1850' TO 1600'. PULLED & LAID DOWN 52 JTS. 2-3/8" TBG. SPOTTED A 25 SK. CEMENT PLUG FROM 250' TO SURFACE. FINISHED TOH W/TOTAL 100 JTS. 2-3/8" TBG. & SETTING TOOL. REMOVED BOP, CUT OFF WELLHEAD AND INSTALLED DRY HOLE MARKER. RDP, CUT OFF ANCHOR & CLEANED LOCATION. WELL PLUGGED & ABANDONED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>R.L. Wheeler, Jr.</u>	TITLE <u>SUPV. ADM. SVC.</u>	DATE <u>5-20-93</u>
		(505)
TYPE OR PRINT NAME <u>R.L. WHEELER, JR.</u>		TELEPHONE NO. <u>393-2144</u>

(This space for State Use)

APPROVED BY <u>Ernie M. Steel</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

OIL &amp; GAS INSPECTOR SEP 20 1993

90  
5-26-93

RECEIVED  
MAY 26 1997  
OCD HOBBS OFFICE