

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Budget Bureau No. 1004-1
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME N. HOBBS (G/SA) UNIT
2. NAME OF OPERATOR SHELL WESTERN E&P INC.	8. FARM OR LEASE NAME SECTION 30
3. ADDRESS OF OPERATOR P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)	9. WELL NO. 331
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface UNIT LTR J, 2335 FSL & 2310' FEL	10. FIELD AND POOL, OR WILDCAT HOBBS (G/SA)
14. XXXXXX API NO. 30-025-07472	11. SEC., T., R., X., OR BLE. AND SURVEY OR AREA SEC. 30, T18S-R38E
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 3654' DF	12. COUNTY OR PARISH LEA
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☒	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This is notification that the proposed work indicated on Form 3160-5 approved 3-28-89 (copy attached) has been cancelled. No further work is planned at this time.

18. I hereby certify that the foregoing is true and correct

SIGNED J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 8-4-89

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

*See Instructions on Reverse Side

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT BLM - CAR

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC 032233 (a)✓

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SHELL WESTERN E&P INC. (4431 WCK)

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

UNIT LETTER J, 2335' FSL & 2310' FEL

7. UNIT AGREEMENT NAME

N. HOBBS (G/SA) UNIT

8. FARM OR LEASE NAME

SECTION 30 ✓

9. WELL NO.

331 ✓

10. FIELD AND POOL, OR WILDCAT

HOBBS (G/SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC. 30, T. 18-S, R 38-E

14. XXXXX API NO.

30-025-07472 ✓

15. ELEVATIONS (Show whether OF, AT, GR, etc.)

3654' DF ✓

12. COUNTY OR PARISH 13. STATE

LEA

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

OAP & AT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- OK (SJS)
- 1) POOH w/ prod equip. ✓
 - 2) CO to 4225'. ✓
 - 3) Perf Grayburg/San Andres 4040' - 4052' w/ 2JSPF.
 - 4) AT San Andres 4118' - 4225' w/ 1500 gals 15% HCl acid + 1000# rock salt.
 - 5) AT Grayburg/San Andres 4014' - 4052' w/ 750 gals 15% HCl acid + 400# rock salt, using RBP and pkr. ✓
 - 6) RIH w/ prod equip and return well to production. ✓

18. I hereby certify that the foregoing is true and correct

SIGNED

W.F.N. KELLDORF

TITLE STAFF PRODUCTION ENGINEER

DATE

3/15/89

(This space for Federal or State office use)

CHIEF, MINERAL RESOURCES

APPROVED BY

TITLE

DATE

3-28-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

MAILED 10 17 AM '89
CARL
ALLEN