

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO LC 032233 (a)	
2. NAME OF OPERATOR SHELL WESTERN E&P INC. (4431 WCK)		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. BOX 576, HOUSTON, TEXAS 77001		7. UNIT AGREEMENT NAME N. HOBBS (G/SA) UNIT	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit letter J, 2335' FSL and 2310' FEL of section 30		8. FARM OR LEASE NAME SECTION 30	
14. PERMITS API #: 30-025-07472		9. WELL NO. 331	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3654' DF		10. FIELD AND POOL, OR WILDCAT HOBBS (G/SA)	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC 30, T 18-S, R 38-E	
		12. COUNTY OR PARISH LEA	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐
(Other) OAP & AT ☒		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) POOH w/ prod equip.
- 2) CO to 4170'.
- 3) Spot 100 gals 15% HCL acid from 4130' up, using CIBP set @ 4150'.
- 4) Perf San Andres 4056' - 4124' w/ 2JSPF.
- 5) AT San Andres 4056' - 4124' w/ 2000 gals 15% HCL acid + 750# rock salt, using CIBP set @ 4150' and pkr set @ 4030'.
- 6) TIH w/ prod equip and return well to production.

Handwritten notes and stamps:
APR 17 1989
S 189

18. I hereby certify that the foregoing is true and correct

SIGNED W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE APR 17 1989

(This space for Federal or State office use)

APPROVED BY Shannon J. Shaw FOR: DATE 4-25-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side