

Form 3100-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Excludes Bureau of Reclamation
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC 032233 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SHELL WESTERN E&P INC.

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

UNIT LTR J, 2335' FSL & 2310' FEL

7. UNIT AGREEMENT NAME

N. HOBBS (G/SA) UNIT

8. FARM OR LEASE NAME

SECTION 30

9. WELL NO.

331

10. FIELD AND POOL, OR WILDCAT

HOBBS (G/SA)

11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA

SEC. 30, T18S-R38E

12. COUNTY OR PARISH 13. STATE

LEA

NM

14. XXXXXXXX API NO.
30-025-07472

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3654' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-25-86: Pulled prod equip. Released RBP @ 4054' & POH.

11-26-86: Tagged btm @ 4192'. PB to 4169' w/4-1/2 sx 16/20 sand. PB to 4161' w/1-1/2 sx cmt.

11-28-86: Set cmt ret @ 3928'. Sqzd Grayburg/San Andres perfs 4010' - 4160' w/100 sx Cls "C" cmt + 2% CaCl₂ + 1.5% Howco sucs + .75% HC-2 followed by 25 sx Cls "C" cmt + 2% CaCl₂.

12-01 to 12-02-86: Tagged TOC @ 3921'. DO cmt (& cmt ret @ 3928') to 4053'. Pres tstd sqzd perfs 4010' - 4045' to 500#, held OK. DO cmt to 4098'. Pres tstd sqzd perfs 4068' - 4092' to 500#, held OK. DO cmt to 4162'. Pres tstd sqzd perfs 4108' - 4160' to 500#, held OK. Circ'd sand out to 4198'. Tagged CIBP @ 4198'.

12-03 to 12-04-86: DO CIBP.

12-06-86: Perf'd San Andres 4170' - 4225' (2 JSPF).

12-08-86: Acid perfs 4170' - 4225' w/1000 gals 15% HCl + 500# rock salt.

12-09-86: Installed prod equip & returned well to prod.

18. I hereby certify that the foregoing is true and correct

SIGNED A. J. Fore A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE DECEMBER 19, 1986

(This space for ACCEPTED FOR RECORD)

APPROVED BY (ORIG. SCD) DAVID R. GLASS

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

JAN 07 1987

CARLSBAD, NEW MEXICO See Instructions on Reverse Side