

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

N. HOBBS (G/SA) UNIT
SEC. 30

1. Type of Well:

OIL
WELL

☒

GAS
WELL

☐

OTHER

2. Name of Operator

Shell Western E&P Inc.

8. Well No.

231

3. Address of Operator

P.O. Box 576 Houston, TX 77001-0576

9. Pool name or Wildcat

HOBBS (G/SA)

4. Well Location

Unit Letter K : 2310 Feet From The SOUTH Line and 2310 Feet From The WEST Line

Section

30

Township

18S

Range

38E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3662' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: WSO & AT ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH W/PROD EQUIP.

2. CO TO TD @ 4256'.

3. SET PKR @ 4050' & PT ANN TO 300#.

4. REL PKR & RESET @ +/-4130'. PMP FW THRU TBG AND/OR DWN BACKSIDE TO TST FOR
COMM. REL PKR & POH.

5. SET CIBP @ +/-4130' (BTW PERFS @ 4123' & 4136').

6. SET CICR @ +/-4050'. ESTAB INJ RT.

7. SQZ SA PERFS 4119-23' W/100 SX CLS C CMT + 2% CACL2. CAP CICR W/10' CMT.
WOC 24 HRS.

8. DO CICR & CMT TO 4125'. PT SQZ TO 500# FOR 15 MIN.

9. DO CIBP @ +/-4130' & PUSH REMNANTS TO TD.

10. ACDZ PERFS 4136-88' & OH 4200-56' W/4000 GALS 15% NEFE HCL + 1500# ROCK SALT.

11. INST PROD EQUIP & RET WELL TO PROD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. H. Smitherman

TITLE

REGULATORY SUPV.

DATE 7/02/91

TYPE OR PRINT NAME

J. H. SMITHERMAN

TELEPHONE NO. 713/870-3797

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: