- POOH w/ prod equip.
- CO to 4140'. 2)
- Spot 100 gals 15% HCl acid from 4112' up, using CIBP set @ 4112'.
- Perf Grayburg/San Andres 4082' 4108' w/ 2JSPF.
- AT Grayburg/San Andres 4082 4108' w/ 900 gals 15% HCl acid + 400# rock salt, using pkr set @ 4074'.
- RIH w/ prod equip and return well to production.

DISTRICT I SUPERVICTOR

and the best of my broaded a mil being	
I hereby certify that the information above is true and complete to the best of my knowledge and believe to the best of the best of my knowledge and believe to the be	STAFE PRODUCTION ENGINEER MAR 2 4 1989
Signature African Signature for W.F.N. KELLDORF TITLE	3 ATT TRODUCTION ENGINEER DATE
TYPE OR PRINT NAME	TELEPHONE NO.
(This space for State Use) ORIGINAL SIGNAL BY SEE SEE STATE ORIGINAL SIGNAL BY SEE SEE SEE STATE ORIGINAL SIGNAL BY SEE SEE SEE SEE SEE SEE SEE SEE SEE SE	MAR 3 () 1989

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY