

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 31 |
| 8. Well No. 411 |
| 9. Pool name or Wildcat HOBBS (G/SA) |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | |
| 2. Name of Operator SHELL WESTERN E&P INC. | |
| 3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4413) | |
| 4. Well Location Unit Letter <u>A</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>330</u> Feet From The <u>EAST</u> Line Section <u>31</u> Township <u>18S</u> Range <u>38E</u> NMPM <u>LEA</u> County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3645' GR | |

| | |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: SET CIBP, OAP & AT <input checked="" type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH W/PROD EQMT.
2. CO TO PBTD @ +/-4159'.
3. SET CIBP @ +/-4125'.
4. SPOT 100 GAL 15% HCL FROM 4125' TO 4000'.
5. PERF SA 4068-80' (2 JSPF).
6. AT PERFS 4068-80' W/1050 GAL 15% NEFE HCL.
7. INST PROD EQMT & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

W. F. N. Kelldorf

TITLE

DIV. ENVIRONMENTAL ENGR.

DATE

11/11/91

TYPE OR PRINT NAME

W. F. N. KELLDORF

(713) 870-3426

TELEPHONE NO.

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY

TITLE

DATE

NOV 14 1991

CONDITIONS OF APPROVAL, IF ANY: