

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-121) FOR SUCH PROPOSALS.)

CIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
SHELL WESTERN E&P INC.

Address of Operator
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

Location of Well
UNIT LETTER A, 330 FEET FROM THE NORTH LINE AND 330 FEET FROM

THE EAST LINE, SECTION 31 TOWNSHIP 18-S RANGE 38-E N.M.P.M.

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT

8. Field or Lease Name
SECTION 31

9. Well No.
411

10. Field and Pool, or Widest
HOBBS (G/SA)

15. Elevation (Show whether DF, RT, GR, etc.)
3645' GR

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER <u>OAP & ACIDIZE</u> ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Pull production equipment. Tag btm.
2. Perf San Andres 4135' - 4141' (2 JSPF, 4 holes).
3. Acidize perf's 4135' - 4252' w/5100 gals 15% HCl-NEA.
4. Install production equipment and return well to production.