

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-07441
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTOR	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 31
2. Name of Operator SHELL WESTERN E&P INC.	8. Well No. 311
3. Address of Operator P.O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter B : 440 Feet From The NORTH Line and 2310 Feet From The EAST Line Section 31 Township 18S Range 38E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3649' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Profile Correction ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-30 to 8-06-88:

POH w/inj equip. CO to 4180'. Set CICKR @ 3904'. Could not pmp thru CICKR. Knocked CICKR to btm. Set 2nd CICKR @ 3935'. Sqzd Grayburg perms 3976'-4067' w/75 SX Cls "C" cmt + 2% CaCl<sub>2</sub>. DO cmt & CICKR 3933'-4056'. Pres tstd sqz to 800#, held OK. Perf'd Grayburg 4010'-41' (2 JSPF). Acd perms 4010'-41' w/1500 gals 15% HCl-NEFE. Installed inj equip, setting Guib Uni-PKR VI @ 3895'. Pres tstd csg to 500# for 30 min, held OK. Retd well to inj.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. F. N. Kelldorf TITLE STAFF PRODUCTION ENGINEER DATE 3-30-89  
TYPE OR PRINT NAME W. F. N. KELLDORF (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

APR 4 1989