

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 31
8. Well No. 321
9. Pool name or Wildcat HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3644' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	2. Name of Operator Shell Western E&P Inc.	3. Address of Operator P.O. Box 576 Houston, TX 77001-0576
4. Well Location Unit Letter <u>G</u> : <u>2200</u> Feet From The <u>NORTH</u> Line and <u>2310</u> Feet From The <u>EAST</u> Line Section <u>31</u> Township <u>18S</u> Range <u>38E</u> NMPM LEA County		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: REPERF'D, ACD & CMT SQZD FOR WSO ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-25 TO 4-04-91:

POH W/PROD EQUIP. CO TO 4292'. SPOT 300 GALS 15% HCL FROM 4243' TO 4180'. PERF'D SA 4188' - 4243' (2 JSPF). ACD PERFS 4188' - 4243' W/1500 GALS 15% NEFE HCL. SET RBP @ 4172', PKR @ 4060'. ESTAB INJ RT INTO PERFS 4147-62'. REL RBP & PKR, POH. SET CIBP @ 4172', CIBR @ 4060'. ESTAB INJ RT. SQZD PERFS 4147-62' W/75 SX CLS C CMT + 350 SCFPB N2. CAP CIBR W/10' CMT. TAG CMT @ 4059'. DO CMT & CIBR TO 4172' (CIBP). PT SQZD PERFS TO 500#, HELD 30 MIN. DRLED UP CIBP, PUSHED REMNANTS TO BTM @ 4284'. INST PROD EQUIP & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 7/11/91
TYPE OR PRINT NAME J. H. SMITHERMAN TELEPHONE NO. 713/870-3797

(This space for State Use) APPROVED BY JERRY JOXSON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUL 16 1991