

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Bureau of Geology, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-07503
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 31
8. Well No. 211
9. Pool name or Wildcat HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3651' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	2. Name of Operator SHELL WESTERN E&P INC.	3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter C : 440 Feet From The NORTH Line and 2310 Feet From The WEST Line Section 31 Township 18S Range 38E NMPM LEA County
--	---	---	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	SUBSEQUENT REPORT OF:		
NOTICE OF INTENTION TO:			
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: Cmt sqzd OAP & Acid ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-19 to 10-27-89:

POH w/prod equip. Set CIBP @ 4157'. Brk dwn selected sqzd perfs 4073' - 4154' w/ 850 gals 15% NEFE HCl. Set CIBP @ 4012'. Estab inj rt. Sqzd perfs 4073' - 4154' w/ 150 sx Cls "C" cmt + 2% CaCl₂ + 1.5% Howco suds + 0.75% HC-2 + 200 SCF N₂/bbl followed by 41 sx Cls "C" cmt + 2% CaCl₂. DO CIBP @ 4012', fell free to 4038'. DO cmt to CIBP @ 4157'. Pres tsld sqz to 500# held. DO CIBP @ 4157' & pushed to btm. Set CIBP @ 4203'. Acid perfs 4172' - 96' w/2000 gals 15% NEFE HCl + 1400# rock salt. Perf'd SA 4128' - 32' (2 JSPP). Set RBP @ 4142'. Acid perfs 4128' - 32' w/500 gals 15% NEFE HCl. Rel RBP & POH. Installed prod equip & rld to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 11-17-89
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NOV 21 1989