NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

ICE OF INTENTION			OW .	
VIANGE PLANS	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
tice of Intention Plug Well	Notice of Intention to Pluc Back		Notice of Intention to Set Liner	
tice of Intention Squeeze	Notice of Intention to Acidize		Notice of Intention to Shoot (Nitro)	
otice of Intention Gun Perforate	Notice of Intention (Other)	X.	Notice of Intention (Other)	
L CONSERVATION COMMISSION TA FE, NEW MEXICO	ON Hobbs, New Mexic	30	April 2	5, 1960
entlemen:				
Following is a Notice of Intention	n to do certain work as described below	w at the Soc	ony Mobil Cil Compan	y, Inc.
(Company or O	Nora Ber	T Y	Weli Noir	(Unit)
NE 1/4 SW 1/4 of Sec.	Note Bel 31 , T. 188 , R 387	,NMPM.	Hobbs	1
(40-acre Subdivision)				
TD 4190 * 7" Cag set @ 3955 w/300	O sks.			
Ran casing leakage test string. Propose to ti	t, had communication between flange bolts, shut ter, pull and inspect wells. Fif unsuccessful willing for leaks.	in, and t llhead fla	est for bulla up. I nges. ring gaskets s	nd replace
Ran casing leakage test string. Propose to ti- will kill well with war all damaged connections	ghten flange bolts, shut ter, pull and inspect well s. \times If unsuccessful will ing for leaks.	in, and t llhead fla	est for bulla up. I nges. ring gaskets s	nd replace
Ran casing leakage test string. Propose to till will with war all damaged connections packer and test 7" cast	ghten flange bolts, shut ter, pull and inspect well s. \times If unsuccessful will ing for leaks.	in, and t llhead fla pull reds	est for bulla up. I nges. ring gaskets s	nd replace
Ran casing leakage test string. Propose to ti- will kill well with war all damaged connections packer and test 7" cas	ghten flange bolts, shut ter, pull and inspect well s \(\neq \text{If unsuccessful will} \) ing for leaks. By Posit	in, and talled flat pull reds	est for build up. Inges, ring gaskets a and tubing, run ret	nd replace

Address Box 2406, Hobbs, New Mexico