

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fed ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

CIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

SHELL WESTERN E&P INC.

Address of Operator

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

Location of Well

UNIT LETTER N 990 FEET FROM THE SOUTH LINE AND 2310 FEET FROM
THE WEST LINE, SECTION 31 TOWNSHIP 18-S RANGE 38-E N.M.P.M.

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT

8. Form or Lease Name
SECTION 31

9. Well No.
241

10. Field and Pool, or Wildcat
HOBBS (G/SA)

15. Elevation (Show whether DF, RT, GR, etc.)

3638' GR

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>Acidz</u> ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify NMOC D at least 24 hrs prior to commencing workover.
2. POH w/prod equip.
3. CO to 4130'.
4. Perf sqz holes @ 3000' (4JSPF). -- TOC @ 3016' (CBL).
5. Set CIBP @ 3950'.
6. Set pkr @ 3030'. Pres tst csg & CIBP to 500#. Rel pkr & reset @ 2950'. Etab inj rt thru perfs @ 3000' & circ to surf. POH w/pkr.
7. Set CICK @ 2950'.
8. Sqz perfs @ 3000' w/300 SX Cls "C" cmt + 2% CaCl₂. Circ cmt to surf WOC 24 hrs.
9. DO CICK & cmt to 3020'. Pres tst sqz. to 500# for 15 min. DO CIBP & CO to TD (4155').
10. Acidz Grayburg perfs 4018' - 4136' & San Andres OH 4141' - 55' w/1200 gals 15% HCl-NEA + 750# rock salt.
11. Install prod equip & ret well to prod.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

DATE 8-10-88 A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 8-10-88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

DATE AUG 15 '88

RECEIVED

AUG 12 1988

OCA
HOBBS OFFICE