

OIL CONSERVATION DIVISION

P. O. BOX 2088
 SANTA FE, NEW MEXICO 87501

Form C-103
 Revised 10-1-78

NO. OF COPIES REQUIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
 State ☐ Fee ☒
 3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REEVAL OR PLUG A WELL TO A DIFFERENT RESERVOIR.
 USE APPLICATION FOR PERMIT - 11 (FORM C-101) FOR SUCH PROPOSALS.

CIL WELL ☒ CAS WELL ☐ OTHER ☐

7. Unit Agreement Name
 N. HOBBS (G/SA) UNIT

Name of Operator
 SHELL WESTERN E&P INC.

8. Form or Lease Name
 SECTION 31

Address of Operator
 P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

9. Well No.
 241

Location of Well
 UNIT LETTER N 990 FEET FROM THE SOUTH LINE AND 2310 FEET FROM
 THE WEST LINE, SECTION 31 TOWNSHIP 18-S RANGE 38-E

10. Field and Pool, or Whose
 HOBBS (G/SA)

11. Elevation (Show whether DF, RT, GR, etc.)
 3638' GR

12. County
 LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	ENHANCE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Repair csg leak	CASING TEST AND CEMENT JOB ☐	OTHER ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.)

1. Pull production equipment. Tag btm.
2. Set a RBP @ 4000'. Dmp 2 sx sand on RBP. Locate hole in csg. Single stage (Step 3) or dual stage (Step 4) sqz will be used depending on hole depth.
- 3.a. Set cmt. retainer 40' above hole. Pmp calculated volume of Class "C" cmt to surf.
 - b. Dmp 1 sk cmt on retainer. WOC 24 hrs.
 - c. Drill out retainer and cmt. Pres tst sqz to 500 psi.
 - d. Circ sand off RBP.
- 4.a. Perforate csg @ 2900'.
 - b. Set cmt retainer @ 2850'. Pmp calculated volume of Class "C" cmt to 50' below hole.
 - c. Dmp 1 sk cmt on retainer.
 - d. Pmp calculated volume of Class "C" cmt. Circ to surface. WOC 24 hrs.
 - e. Drill out cmt to 40' below hole. Pres. tst sqz to 500 psi.
 - f. Drill out retainer and cmt. Pres tst sqzd perfs to 500 psi.
 - g. Circ sand off RBP.
5. Install production equipment and return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE DECEMBER 16, 1985

ORIGINAL SIGNED BY JERRY SEXTON
 DISTRICT 1 SUPERVISOR

DEC 23 1985

RECEIVED
DEC 20 1985
P.C.D.
HOMES OFFICE