

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>7. Unit Agreement Name</p>
<p>2. Name of Operator SUN OIL COMPANY</p>		<p>8. Farm or Lease Name Clara Fowler</p>
<p>3. Address of Operator P. O. Box 1361, Midland, Texas 79701</p>		<p>9. Well No. 1 3</p>
<p>4. Location of Well UNIT LETTER E, 1650 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 18S RANGE 38E RMPM.</p>		<p>10. Field and Pool, or Wildcat Dowers</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3254 DF</p>		<p>12. County Lea</p>

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input checked="" type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>
<p>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.</p>	

- 1) MIRU pulling unit
- 2) Pull rods, pump and tbq.
- 3) Run tbq. open ended. Spot 15 sx cmt. plug 3319-3170. Pull up and WOC 4 hrs.
- 4) Tag plug and circulate hole w/9.5# mud.
- 5) Spot 10 sx cmt. plug 1730 to 1630 inside 5 1/2" csg. Top of salt 1680.
- 6) Spot 15 sx cmt plug at surface, weld on cap and install permanent marker.

Use Class "H" cmt, 9.5# mud laden fluid between plugs.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED

Expires 8-1-77

<p>18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.</p>		
<p>SIGNED <u><i>Charles Gray</i></u></p>	<p>TITLE <u>Proration Analyst</u></p>	<p>DATE <u>7/20/76</u></p>
<p>APPROVED BY _____</p>	<p>TITLE _____</p>	<p>DATE _____</p>
<p>CONDITIONS OF APPROVAL, IF ANY:</p>		

RECEIVED
JUL 21 1976
NEW CONSERVATION COMM.
HOBBS, N. M.