

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- INJECTOR	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name SECTION 31
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 121
4. Location of Well UNIT LETTER E 1980 FEET FROM THE NORTH LINE AND 990 FEET FROM THE WEST LINE, SECTION 31 TOWNSHIP 18-S RANGE 38-E NMPM.	10. Field and Pool, or WHdcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3665' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER CONVERT TO UPPER/LOWER GRAYBURG INJ. <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

PMX-89

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- CO to TD (4189'). Set RBP @4070'. Run CBL/VDL/CCL/GR logs from 4070' to surface. Spot 200 gals 15% NEA HCl acid.
- Perf 7" csg 4056', 4058', 4060', 4064' (16 holes). Acidize with 1700 gals 15% NEA HCl acid.
- Spot 380 gals 15% NEA HCl acid. Acidize OH interval (4075' - 4189') w/4400 gals 15% NEA HCl acid.
- Set pkr @3970'. Take injectivity test and complete.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Carter for A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MARCH 30, 1982

APPROVED BY Les Clements DATE APR 1 1982

CONDITIONS OF APPROVAL, IF ANY: