

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name SECTION 32
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 111
4. Location of Well UNIT LETTER D 660 FEET FROM THE NORTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 32 TOWNSHIP 18-S RANGE 38-E N.M.P.M.	10. Field and Pool, or WHdcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3646' GR	12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER OPEN ADDITIONAL PAY AND ACIDIZE <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spot 100 gals 15% NEA-HCl @ 4215'.
- Perforate 4110' - 12', 4142' - 44', 4165' - 68', 4188' - 90', 4195' - 97' and 4211' - 13' (38 holes).
- Acidize SA IIIu and II w/3500 gals 15% NEA-HCl.
- Install production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY Jerry Sexton TITLE SUPERVISOR REG. & PERMITTING DATE JANUARY 11, 1983
APPROVED BY JERRY SEXTON DISTRICT 1 SUPERVISOR TITLE DISTRICT 1 SUPERVISOR DATE JAN 17 1983