

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-75

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

|                                           |                              |
|-------------------------------------------|------------------------------|
| 5a. Indicate Type of Lease                |                              |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.              |                              |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ CAS WELL ☐ OTHER

2. Name of Operator

ELL WESTERN E&P INC.

3. Address of Operator

O. BOX 991, HOUSTON, TEXAS 77001

4. Location of Well

6. LETTER N 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM  
WEST LINE, SECTION 33 TOWNSHIP 18-S RANGE 38-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3637' GR

7. Unit Agreement Name

N. HOBBS (G/SA) UNIT

8. Form or Lease Name

SECTION 33

9. Well No.

241

10. Field and Pool, or Wildcat

HOBBS (G/SA)

12. County

LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

REMEDIAL WORK ☐  
WILT ABANDON ☐  
ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒  
COMMENCE DRILLING OPER. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations.)  
SEE RULE 1103.

PED ACID & SCALE SQUEEZED

3-84: Dumped 1000 gals 15% HCl-NEA down csg annulus. Let acid set 15 min. Mixed and pumped 110 gals Nalco 4987 & 5 gals ODS-980 in 75 bbls 9# brine wtr. Flushed w/ 120 bbls 9# brine.

4-84: Returned well to production.

Certify that the information above is true and complete to the best of my knowledge and belief.

A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE JUNE 25, 1985

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

TITLE

DATE JUL - 1 1985

RECEIVED

JUN 28 1985

O.C.C.  
HOBAS CTR