

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Continental Oil Company	5. State Oil & Gas Lease No. B-2656
3. Address of Operator Box 460, Hobbs, New Mexico	7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>M</u> <u>585</u> FEET FROM THE <u>WEST</u> LINE AND <u>585</u> FEET FROM THE <u>SOUTH</u> LINE, SECTION <u>33</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> NMPM.	8. Farm or Lease Name STATE A-33
	9. Well No. 9
	10. Field and Pool, or Wildcat Brewer 7 River & Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3639' DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug & abandon this well by the following procedures:

Spot a 40 SX Cmt plug from TD (3235) to cover parts from 3100' to 3170'. Fill well bore with 10# mud and set a 10 SX Cmt plug at surface. Cap with dry hole marker & restore location.

N.M.O.C.C. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>M. E. H. [Signature]</u>	TITLE <u>Administrative Section Chief</u>	DATE <u>12-2-70</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>[Signature]</u>
CONDITIONS OF APPROVAL, IF ANY:		