

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2656
7. Unit Agreement Name
8. Form or Lease Name State A-33
9. Well No. 11
10. Field and Pool, or Wildcat Bowers Seven Rurs
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- shot-in
2. Name of Operator CONOCO INC.
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240
4. Location of Well UNIT LETTER G , 2310 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 33 TOWNSHIP 18S RANGE 38E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- ① MIRU. RHT w/ workstring, open ended to 3100' & circ. wellbore w/ mud (approx 76 bbls) Spot a ^{25 SX} 10 sx cmt plug from 2850'-2750'. Tag TOC.
- ② Spot a ^{25 SX} 10 sx cmt plug from 1613'-1513'. Spot a 10 sx-cmt plug from 452'-352'. Tag TOC.
- ③ Spot 10 sx cmt plug from 100' to surface. Cut off csg @ base of cellar. Fill hole w/ sand, cmt, gravel, etc.
- ④ Erect P & A marker, clean location and rig down.
- ⑤ A P & A sketch is attached.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Paul Kautz* TITLE Administrative Supervisor DATE 10-20-86

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE OCT 23 1986

CONDITIONS OF APPROVAL, IF ANY:

NMOCB-Hobbs(3)

RECEIVED

OCT 22 1986

CC
HOBBS OFFICE