

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE OCC

MISCELLANEOUS REPORTS ON WELLS

1954 MAY 6 PM 3:25

Hobbs, New Mexico

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

result of well repair, and other import instructions in the Rules and Regulatio				ion. See additiona
		port by checking be	·····	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RES OF CASING SHU	ULT OF TEST I-OFF	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON REC OPERATION	OMPLETION	REPORT ON (Other) Repaired G	g. loak X
	May (Date	5 , 1954	Hobbs, Nen	Mexico (Place)
Following is a report on the work	done and the results obtained	d under the heading n	oted above at the	
Gulf Oil Corpe (Company or O	pration	N.	D. Grimes (Lease)	NCT-B
Clarke 011 Well S	Servicing Co.	, Well No3	in the W 1/4 NE	1/4 of Sec. 33
T 18-S , R 38-E , NMPM., Hebbs		Pool,	Les	County
The Dates of this work were as folows:	April 12 thru	29, 1954		
Notice of intention to do the work (was	s) (xat) submitted on Form	n C-102 on	Kerch 15.	, 19. 54 ,
and approval of the proposed plan (was	s) (obtained.		(Cross out incorrect words)	
DETA	ILED ACCOUNT OF WORK	DONE AND RESUI	LTS OBTAINED	
SEE ATTACHED SHE	at .			
Witnessed by	m Gulf	Oil Corporati	On Pield For	(Amer)
Approved: OIL CONSERVATION	COMMISSION	I hereby certify that to the best of my ki	t the information given above is nowledge.	true and complete
(Name)	Lize	Name.	Jaja	
	MAY year	Position	Area Prod. Supt.	<u></u> .
, ,	Marin Control of the	erchreaming	······································	***************************************

(Date)