

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name SECTION 33
3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001	9. Well No. 221
4. Location of Well UNIT LETTER F, 2310 FEET FROM THE NORTH LINE AND 1320 FEET FROM THE WEST LINE, SECTION 33 TOWNSHIP 18-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3643' GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER WATER SHUT-OFF <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- Clean out to TD 4242'.
- Set cmt retainer @ 3950'. Squeeze cement perms 4043' to 4052' w/50 sx Class "C" cement containing 2% CaCl₂. WOC 24 hrs.
- Drill out cement to 4060'+. Pressure test squeeze to 500 psi.
- Install production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Cortez A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE APRIL 13, 1983
APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR TITLE DATE APR 20 1983
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 18 1983

O.C.D.
HODES OFFICE