

DISTRICT 1

1625 N. French Drive, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO.	30-025-07578
5. Indicate Type of Lease FED <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		SECTION 34
2. Name of Operator OCCIDENTAL PERMIAN, LTD.		8. Well No. 221
3. Address of Operator 1017 W STANOLIND RD.		9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter <u>F</u> <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1700</u> Feet From The <u>WEST</u> Line Section <u>34</u> Township <u>18-S</u> <u>38-E</u> NMPM LEA County		
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3625' GL		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>TEMPORARY ABANDON</u>	<input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POOH W/PRODUCTION EQUIPMENT. LAYING DOWN ESP EQUIPMENT.  
 RHH W/5" CSG SCRAPER TO 4090'.  
 SET 5" CIBP @4084'. TOP PERF @4102'.  
 TEST CSG TO 500 PSI FOR 30 MIN AND CHART FOR THE NMOCD. \*\*\*\* NOTIFY NMOCD 24 HRS BEFORE CSG TEST.  
 CIRC CSG WITH INHIBITED FLUID.  
 POOH LAYING DOWN TBG.  
 RDPU AND CLEAN LOCATION.

WELL IS TEMPORARY ABANDONED.

RIG UP DATE: 06/12/2000  
 RIG DOWN DATE: 06/15/2000

This Approval of Temporary  
Abandonment Expires 7/31/2005

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE LIFT SPECIALIST DATE 07/11/2000  
 TYPE OR PRINT NAME R.N. GILBERT TELEPHONE NO. 505/397-8206

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE DISTRICT SUPERVISOR DATE 7/11/2000

ORIGINAL SUBMITTED TO THE DISTRICT SUPERVISOR

2





