

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name SECTION 34
3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001	9. Well No. 441
4. Location of Well UNIT LETTER P, 400 FEET FROM THE SOUTH LINE AND 1190 FEET FROM THE EAST LINE, SECTION 34 TOWNSHIP 18S RANGE 38E NMPM.	10. Field and Pool, or Wildcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3620' GR	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Displace hole with mud laden fluid.
2. Spot Class "C" neat cement plugs as follows:

Required Location of Plug	Base of Plug	Top of Plug	Cement Volume
100' above top of Grayburg	4233'	3822'	42 sx
Across Bowers	3571'	3355'	23 sx
50' above & below base of the salt	2740'	2640'	11 sx

3. Perforate at top of salt (1750') with a 4-way jet gun.
4. Spot a 1100' cement plug from 1750' with 330 sx Class C neat. A 300' plug is required above the Salt from the formation to the middle of the hole.
5. Spot a 78 sx Class "C" neat cement plug from 760' to surface (3').
6. Cut casing off 3' below ground level and weld on a dry hole marker. Clean and level location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MARCH 7, 1984

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE

DATE MAR 13 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
MAR 12 1984  
O.C.D.  
HQS. OFFICE