

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Continental Emsco Co.		8. Farm or Lease Name Pearl Goode	
3. Address of Operator c/o Oil Reports & Gas Services, Inc. - Box 763 - Hobbs, N.M. 88240		9. Well No. 4	
4. Location of Well UNIT LETTER D 330 FEET FROM THE N LINE AND 660 FEET FROM THE W LINE, SECTION 31 TOWNSHIP 18S RANGE 39E NMPM.		10. Field and Pool, or Wildcat E. Hobbs-San Andres	
15. Elevation (Show whether DF, RT, GR, etc.) 3608 RT		12. County Lea	

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows:

Set 5½" Bridge Plug @ 4300' & dump 3 sacks cement on top  
Circulate hole w/mud  
Cut and pull 5½" @ 1235'  
100' plug across casing stub  
100' plug across 10 3/4 shoe @ 323'  
10 sacks plug @ surface  
Mud between all plugs  
Location clean & leveled

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Marion Keller TITLE Agent DATE 7/16/76

APPROVED BY John W. Runyan TITLE  DATE DEC 10 1976

CONDITIONS OF APPROVAL, IF ANY: