FE U.S.G.S.	NEW MEXICO OIL CONSERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 5a. Indicate Type of Lease State X Fee.
LAND OFFICE OPERATOR		5. State Oil & Gas Lease No.
SUNDRY	NOTICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. N FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS WELL WELL X	OTHER-	7. Unit Agreement Name 8. Farm or Lease Name
2. Name of Operator DASSOIL Well Servicing, Incorporated		State 32
P. O. Box 657, Hobbs, New Mexico 88240 4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER B , 330	FEET FROM THE North LINE AND 410 FEE	Texline Penrose Gas
THEEast LINE, SECTION	32 TOWNSHIP 185 RANGE 39E	
	15. Elevation (Show whether DF, RT, GR, etc.) 3600 GL	12. County Lea
16. Check A	ppropriate Box To Indicate Nature of Notice, Report	or Other Data QUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS OTHER OTHER	ALTERING CASING PLUG AND ABANDONMENT
	erations (Clearly state all pertinent details, and give pertinent dates, in	scluding estimated date of starting any proposed
1. Run 2 7/8" CIBI	e set @ 3800'. Cap with 2 sx. cmt.	
2. Cut 2 7/8" csg. cmt plug top o	at 3000'. Break circulation thru 2 7/8" f stub.	csg. & spot 50 sx.
3. POH with 2 7/8	1 & spot 50 sx cmt plug base of 8 5/8 11 from	₁ 1890 - 1760 ft.
4. Lay down remain		
	plug in surface of 8 5/8".	
6. Install dry ho	le marker & clean location.	