State of New Mexico Energy, M² als and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

1.0. Box 1980, 11000s, 14M 88240	310 Old Santa Fe Trail, Room 206 Santa Fe, New Mexico 87503		WELL APIN	O.			
			30-015-09921				
		- W 1/13/1260 G / 3 G S	5. Indicate T	U Z S	V C/A	<u> </u>	
			_				
			FED	STATE	X FEE		
			o. State Oil 8	Gas Lease No.			
SUNDRY NO	TICES AND DEPORTS ON V	WELL C	<i>!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!</i>				
SUNDRY NOTICES AND REPORTS ON WELLS							
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Nam	ie or Unit Agreei	ment Name		
(FORM C-101 FOR SUCH PROPOSALS.)			N. HODIZS GRAYBURG/SAN ANDRES 4/17				
1. Type of Well:			GRAYBUR	G/SAN ANDR	ES 4/1/7		
Oil Well X Gas Well Other DIECTOR					·		
2. Name of Operator				401			
ALTURA ENERGY LTD.				8. Well No. 421			
3. Address of Operator			9. Pool name	or Wildcat	 -		
1710 WEST STANOLIND RD, HOBBS, NM 88240 505/397-8200 4. Well Location			HOBBS GB/SA.				
4. Well Location				,,			
Unit Letter H 1650	Feet From The NORTH	Line and 330 Fee	. C	7.00			
	North		t From The	EAST	Line	Ī	
Section 36	Township 18-S	Range 37-E	. NMI	РМ	LEA Cour		
	10. Elevation (Show whether DF,	RKB, RT GR, etc.)			LEA Cour	11.	
	3658' DF						
11. Che	eck Appropriate Box to Indicate	Nature of Notice, Report, o	or Other Data	<u> </u>			
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT R	EPORT OF:			
PERFORM REMEDIAL	PLUG AND	REMEDIAL WORK	` —				
WORK	ABANDON	ILLINEDIAE WORK	1 1	ALTERING	CASING		
TEMPORARILY ABANDON X	CHANGE PLANS	COMMENCE DRILLING OP	Ne 🗀	DI LIC 4 AF		_	
PULL OR ALTER CASING	<u> </u>			PLUG & AE	BANDONMENT		
OTHER:		CASING TEST AND CEMEN	IL 10B				
		OTHER:					
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	rations (Clearly state all pertinent detail	ls, and give pertinent dates, includ	ling estimated de	ite of starting an	v proposed		
work) SEE ROLE 1103.				, , ,	, p. spessu		
NOTIFY THE NMOCD OF RIG U)						
POOH WITH PRODUCTION EQUIPMENT.							
RIH W/5.5" CSG SCRAPER TO 4025'. (CSG 5.5" – 15.5#)							
SET 5.5" CIBP @4000'. TOP PERF @4044'.							
TEST CSG TO 500 PSI FOR 30 MIN AND CHART FOR THE NMOCD. NOTIFY THE NMOCD 24 HR BEFORE CSG TEST.							
CIRC CSG WITH INHIBITED FLU	ID	D. NOTIFY THE NMOCD 2	4 HR BEFOR	E CSG TEST.			
RDPU. CLEAN LOCATION.							
I hereby certify that the information above	is true and complete to the best of my k	nowledge and helief					
$\mathcal{I}/\mathcal{I} + \mathcal{I}$	24 11 1						
SIGNATURE A Soul //.	Lillet	TITLE LIFT SPECIALI	ST	DATE	8-17-	98	
TYPE OR PRINT NAME R.N. GILB	ERT						
			NO.	EPHONE	505/397-820	6	
(This space for State Use) ORIGIA	ML SIGNED BY					===	
APPROVED BY	ATTORIONAL						