

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator

Shell Western E&P Inc.

3. Address of Operator

P.O. Box 576 Houston, TX 77001-0576

(wck 4587)

7. Lease Name or Unit Agreement Name

N. HOBBS (G/SA) UNIT
SECTION 20

8. Well No.

241

9. Pool name or Wildcat

HOBBS (G/SA)

4. Well Location

Unit Letter N : 330 Feet From The SOUTH Line and 2310 Feet From The WEST Line

Section 20 Township 18S Range 38E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3652' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: WSO, OAP, REPERF & ACD ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-26 TO 3-02-92:

POH W/PROD EQMT. CO TO PBTD. SET CIBP @ 4210'. PERF SA 4183-96' (2 SPF). ACD PERFS 4183-96' W/1260 GAL 15% NEFE HCL. INST PROD EQMT & RTP.

3-17 TO 3-27-92:

POH W/PROD EQMT. SET CIBP @ 4173'. SQZD PERFS 4183-96' W/150 SX CLS C CMT + 2% CACL2 + 1.5% HOWCO SUDS + .75% FOAM STBLZR + 300 SCF/BBL N2 FOLLOWED BY 50 SX CLS C CMT + 2% CACL2. LEFT 1 BBL CMT ON TOP CIBP. DO CMT 4106-57'. FOUND CIBP @ 4158'. DRLD UP CIBP & CMT TO 4173'. PT SQZ TO 500#, HELD. PERF GRAYBURG 4149-66' (2 SPF). ACD PERFS 4149-66' W/750 GAL 15% NEFE HCL. DO CMT 4173-80'. PERF G/SA 4168-73' (2 SPF). ACD PERFS 4149-73' W/1480 GAL 15% NEFE HCL. INST PROD EQMT & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

W. F. N. Kelldorf

TITLE

TECH. MANAGER - ENVIR. ENG.

DATE 5/20/92

TYPE OR PRINT NAME

W. F. N. KELLDORF

TELEPHONE NO. 713/870-3426

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 27 '92