

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-12497

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Shell Western E&P Inc.

3. Address of Operator

P.O. Box 576 Houston, TX 77001-0576

4. Well Location

Unit Letter L : 2310 Feet From The SOUTH Line and 330 Feet From The WEST Line

Section 28

Township 18S

Range 38E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3639' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: WSO, REPERF'D & ACD ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-03 TO 4-19-91:

POH W/PROD EQMT. SET RBP @ 4161' & PKR @ 4105'. ESTAB INJ RT INTO LK'G SA PERFS 4124-51'. RESET RBP/PKR, SAME RESULT. REL PKR & RBP, POH. SET CIBP @ 4161' & CIGR @ 4005'. SQZD SA PERFS 4048' - 4151' W/100 SX CLS C NEAT CMT + 350 SCF/BBL N2 FOLLOWED BY 50 SX CLS C CMT + 2% CACL2. LEFT 5' CMT ON TOP OF CIGR. DO CMT 4000-05'. DO CIGR & CMT TO 4090'. PT SQZ TO 500# FOR 30 MIN, HELD. CONT DRLG OUT CMT TO 4161' (TOP OF CIBP). PT SQZ TO 500# FOR 30 MIN, HELD. DRLD UP CIBP TO 4163'. SQZ COMM W/ LOWER PERFS. DO CMT TO PETD @ 4262'. PT PERFS 4165' - 4230' & OH 4233-65' TO 500#, BLED OFF 200# IN 1 MIN. REPERF'D 4165' - 4224' (2 SPF). ACD PERFS 4165' - 4224' W/ 2750 GALS 15% NEFE HCL + 500# ROCK SALT. SET CIBP @ 4043'. PERF'D SA 4032-38' (2 SPF). ATTEMPTD TO ACD PERFS 4032-38' W/500 GALS 15% NEFE HCL, COULD NOT PMP INTO PERFS. KO CIBP & CO HOLE. INST PROD EQMT & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 7/19/91

TYPE OR PRINT NAME J. H. SMITHERMAN

TELEPHONE NO. 713/870-3797

(This space for State Use)

DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 25 1991

COB
HOBBS OFFICE