

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPCUT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-121) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

SHELL WESTERN E&P INC.

Address of Operator

P. O. BOX 576, HOUSTON, TEXAS 77001

Section of Well

UNIT LETTER G 1650 FEET FROM THE NORTH LINE AND 2310 FEET FROM
THE EAST LINE, SECTION 32 TOWNSHIP 18S RANGE 38E N.M.P.M.

7. Unit Agreement Name

N. HOBBS (G/SA) UNIT

8. Field or Lease Name

SECTION 32

9. Well No.

321

10. Field and Pool, or Wholeness

HOBBS (G/SA)

11. Elevation (Show whether DF, RT, GR, etc.)

3628' GR

12. County

LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

FOR REMEDIAL WORK ☐
FOR ABANDON ☐
FOR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER PB TO BASE OF SAN ANDRES ZONE I ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

1. Pull production equipment.
2. Run crossflow check in OH 3950' - 4275'.
3. PB to approx. 4070' w/sand.
4. PB from 4070' to 4048' w/hydromite.
5. Install production equipment and return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

A. J. FORE
Orig. Signed by
Paul Kautz
Geologist

TITLE SUPERVISOR REG. & PERMITTING

DATE AUGUST 19, 1986

TITLE

DATE AUG 22 1986