

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name N. HOBBS (G/SA) UNIT	
2. Name of Operator SHELL OIL COMPANY		8. Farm or Lease Name SECTION 13	
3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001		9. Well No. 441	
4. Location of Well UNIT LETTER P, 330 FEET FROM THE SOUTH LINE AND 330 FEET FROM THE EAST LINE, SECTION 13 TOWNSHIP 18-S RANGE 37-E N.M.P.M.		10. Field and Pool, or Wildcat HOBBS (G/SA)	
15. Elevation (Show whether DF, RT, GR, etc.) 3673' DF		12. County LEA	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER WATER SHUT-OFF <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

- Spot sand to 4138' (approx 1650#).
- Perforate San Andres zone I with four-way jet gun @ 4113'.
- Set CICR @ 3870'+. Pump 50 sx Class "C" cement w/2% CaCl₂ plus .3% Halad-4. WOC a minimum of 24 hrs.
- Drill out cement and pressure test squeeze to 500 psi for 15 mins. Clean out sand.
- Install production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE AUGUST 8, 1983

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

AUG 12 1983

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 11 1983
O.C.D.
HOBBS OFFICE