

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Marathon Oil Company	8. Farm or Lease Name Warn State A/C 2
3. Address of Operator P. O. Box 2409, Hobbs, New Mexico 88240	9. Well No. 10
4. Location of Well UNIT LETTER <u>K</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>2233</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>18-South</u> RANGE <u>35-East</u> N.M.P.M.	10. Field and Pool, or Wildcat Vacuum Abo, <del>North</del> <u>North</u>
15. Elevation (Show whether DF, RT, GR, etc.) GL 3978'; KDB 3990'	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Cement Squeeze</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Rig up pulling unit and pull rods, pump, and tubing.
- Run Cement Bond log to determine top of cement.
- Set retrievable BP below cement top and dump sand on top.
- Perforate casing based on Bond Log.
- Go in hole with tubing and retrievable squeeze tool and attempt to circulate.  
If well circulates, cement casing to surface.  
If well does not circulate, squeeze perfs with cement. Will contact N.M.O.C.C. for further verification of procedure.
- Run Temperature Log to find cement top.  
Continue until cement is circulated or until each zone is isolated.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Engineer DATE December 2, 1977  
Orig. Signed by John Bryan  
APPROVED BY [Signature] TITLE Geologist  
CONDITIONS OF APPROVAL, IF ANY:

DEC 5 1977  
DATE