

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.
30-025-20053

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

New Mexico R State (NCT-1)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator Chevron USA, Inc.

8. Well No.
6

3. Address of Operator 15 Smith Rd. Midland, Tx 79705

9. Pool name or Wildcat
Vacuum Yates 62400

4. Well Location

Unit Letter H : 2310 feet from the north line and 760 feet from the east line

Section 6 Township 18-S Range 35-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24hrs prior to MI & RU

2. RIH Tag 2 7/8 CIBP @ 3050, spot 65sx plug 3050-420 (Yates) WOC Tag.

3. Perf 4 holes @ 420, sqz 100sx plug 2 7/8X 8 5/8 to surf from perfs @ 420(11 3/4 shoe, surface)WOC Tag.

* Records show well was perf'd & sqz'd w/500 sxs thru perfs @ 3100 in 9/4/81, If unable to pump into perfs.
Fill 2 7/8 csg w/10sx cmt 420-surf.

4. Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G.R. Bledsoe TITLE HES Specialist DATE 11/1/2002

Type or print name G.R. Bledsoe

Telephone No. 915.687.7153

(This space for State use)

APPROVED BY

TITLE

Conditions of approval, if any:

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE 11-7-2002