

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-871	
7. Unit Agreement Name	
7. Name or Lease Name New Mexico 'AE' State	
8. Well No. 6	
10. Field and Pool, or Wildcat Vacuum Abo Reef	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator TEXACO Inc.	
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	
4. Location of Well UNIT LETTER L , 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 18-S RANGE 34-E N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.) 3996 (DF)	

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER Water Shut Off <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following work has been completed on subject well:

1. Pull rods and pump.
2. Pump 50 bbls of lease crude containing 2 gallons of HyFlo II.
3. Pump 5 bbls of diesel oil containing 2 gallons of HyFlo II.
4. Pump 100 sx Class 'H' cement mixed w/500 gals diesel oil containing 4 gals of DOC-3. Pump 5 bbls diesel oil.
5. Displace w/50 bbls lease oil.
6. Ran 1-5/8" drill pipe, spotted 500 gal 15% MCA acid over perforations 8556 to 8586'. Pull drill pipe.
7. Ran rods and pump, test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE **Assistant District Superintendent** DATE **February 23, 1970**
APPROVED BY [Signature] TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: