

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20160
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-6704
7. Lease Name or Unit Agreement Name Vacuum Abo Unit Btry 1, Tract 15
8. Well No. 4
9. Pool name or Wildcat Vacuum Abo Reef

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook St., Odessa, TX 79762	4. Well Location Unit Letter <u>E</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>8</u> Township <u>18-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3971' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Temporary abandon wellbore ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-17-92: NMOCD notified prior to starting procedure. MI and RU DDU. GIH with CIBP and set at 8750'. Top of perms at 8848'. GIH with workstring to 8745'. Circ. hole with inhibited brine. Test casing to 500# and record on chart. Held OK. COOH and lay down workstring. RD DDU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supervisor, Reg. Affairs DATE 9/22/92  
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. 915/368-1488

(This space for State Use)

APPROVED BY JERRY SEATON TITLE Supervisor, Reg. Affairs DATE 9/22/92

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary  
Abandonment Expires 7-25-97

SEP 28 '92

PRINTED IN U.S.A. 9

DAY

Phillips Pet.

TEJAS  
INSTRUMENT ENGINEERS

VAC. Abc. 15-4  
9/17/92

METER NUMBER

TIME PUT ON

DATE PUT ON

19

BR-B 0-1500-8

SIGNED

TUBE & ORIF. SIZE

TIME TAKEN OFF

DATE TAKEN OFF

19

NIGHT

Vacuum ABO 15-4  
Leg 1: 1650' FWL & 330' FWL,  
Sec. 8, T-18-S, R-35-E  
Lea County, New Mexico