Form. 31605 (November 1053) (Formerly 9331)  BUREAU OF LAND MANAGEMENT  U''TED STATES SUBMIT IN TR (Other lustruct verse side)  BUREAU OF LAND MANAGEMENT							Budget Barcan No. 1004—( Expires Adjust 31, 1985  5 LEASE DESIGNATION AND SERIAL S  NM35612		
			OTICES AND Reposals to drill or to dication for permi		ON WELLS  ck to a different reservoir.  oposals.)	-	6 IF INDIAN, ALLOTTEE OR 1	BIBE NAME	
1.	OIL GAS OTHER						7. UNIT AGREEMENT NAME		
2.	2. NAME OF OPERATOR						8. FARM OR LEAST NAME		
	Anadarko Petroleum Corporation						Polewski Fed		
							B. WELL NO.		
4.	P.O. Box 806 Eunice, NM 88231  LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below)  At surface Sec 31, TWP 19S, Rge 32E  660' FNL & 660' FWL  At top prod. interval: same						West Lusk-Delaware  11. SEC., T. R., M., OR BLE. AND BURYEY OR AREA Sec 31, T 195, R 321		
	A <u>1</u>	t total de	epth: same				320 31, 1 132,	10 321	
14.	300	25 20161	3518.0	Show whether DF.	RT, GR. etc.)		12. COUNTY OR PARISH 13. Lea N		
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data								
	NOTICE OF INTENTION TO:					BSEQUE	T REPORT OF:		
	TEST WATER SE	HUT-OFF	PULL OR ALTER CASI	NG	WATER SHUT-OFF	—.	REFAIRING WELL		
	FRACTURE TREAT	i	MULTIPLE COMPLETE		FRACTURE TREATMENT	<u> </u>	ALTERING CASING		
	SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING REPAIR WELL CHANGE PLANS (Other)					i	ABANDON MENT*		
		ent squee:	ze perfs		(Note: Report re Completion or Re	COMPDIED	multiple completion on We		
17.	proposed work nent to this we	ED OR COMPLETED ( k. If well is direc ork.) *	OFERATION (Clearly St ctionally drilled, give	ate all pertinent subsurface location	details, and give pertinent (one and measured and true v	lates, in ertical	icluding estimated date of s depths for all markers and	tarting any zones perti	
	1. (5-3-88) RUPU TOH w/production string.								
	2. TIH w/PKR on 2 7/8" tbg & set @ 5300'.								
<ol> <li>Cement squeeze perfs: 6390, 6388, 6366, 6364, 6362, 6360, 635 6354, 6336, &amp; 6334 (11 shots) w/100 SX Class H cement.</li> </ol>								6356	
	4. Dri	Drill out cement in csg $w/4$ 3/4" bit, test squeeze 1000 PSI.							
	5. Circ sand off RBP @ 6900' & TOH w/ RBP.								
	6. TIH w/ production string & put back on production. RDPU.								
10	7 hasaba aaa	.ho .ho .	7						

de

TITLE .

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: