NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.	<del>-      </del>	5a. Indicate Type of Lease State Fee
OPERATOR		State Oil & Gas Lease No.
- OT LIVITOR		B-1031
(DO NOT USE THIS	SUNDRY NOTICES AND REPORTS ON WELLS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  15E "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. 01L <b>70</b> 64	AS OTHER-	7. Unit Agreement Name
2. Name of Operator TEXACO Inc	•	8. Farm or Lease Name  New Mexico 'AB' St.
3. Address of Operator	728, Hobbs, New Messico 88240	9. Well No.
4. Location of Well	J 1800 FEET FROM THE South LINE AND 1650 FEET	10. Field and Pool, or Wildcat  Vacuum Abo Reef
ONTI CETTER		FROM VECTORIAL RANGE REST
THE East		ммрм.
	15. Elevation (Show whether DF, RT, GR, etc.)  3982 DF	12. County Lea
16. NOT	Check Appropriate Box To Indicate Nature of Notice, Report of TICE OF INTENTION TO:  SUBSEQUENTIAL STREET OF THE PROPERTY OF T	r Other Data JENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING	COMMENCE DRILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
	OTHER	
OTHER Perfora	ate & Actdize X	
work) SEE RULE 110:	Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc. 3.  Perforate 2 7/8" casing w/ 1 JSPF @ 8172, 88 56,66, 75, 81, 94, 8304, 10, 23, 39, 47, 59, 8400, 07, 26, & 8445'.	3 8 <b>2</b> 07 10 33
2. 1	Acidize w/ 4000 gals. 20% NEA in 4-1000 gal. stages.	
		. stages.
	Swab, Test & Return to production.	. stages.
3. 8	·	. Stages.
3. 8	Swab, Test & Return to production.	

APPROVED BY \_\_\_

CONDITIONS OF APPROVAL, IF ANY: