

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20204
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1258-1
7. Lease Name or Unit Agreement Name NEW MEXICO "AE" STATE
8. Well No. 12
9. Pool name or Wildcat VACUUM ABO REEF
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3998' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P. O. Box 730 Hobbs, NM 88240

4. Well Location Unit Letter <u>D</u> : <u>990</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line County <u>LEA</u> Section <u>12</u> Township <u>18-S</u> Range <u>34-E</u> NMPM <u>LEA</u>
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1). Notify NMOC before plugging.
- 2). MIRU pulling unit. Install BOP.
- 3). By wireline, set CIBP at 8150'. Cap w/35' of class "C" cmt.
- 4). Set CIBP at 6540'. Cap w/35' of class "C" cmt.
- 5). Set CIBP at 4800'. Cap w/35' of class "C" cmt.
- 6). ~~Set CIBP at 3250'. Cap w/35' of class "C" cmt.~~ *Set cement plug 3205-3205 + Tag*
- 7). Set CIBP at 3880'. Cap w/35' of class "C" cmt.
- 8). Set CIBP at 1720'. Cap w/35' of class "C" cmt.
- 9). ~~Set CIBP at 380'. Cap w/35' of class "C" cmt.~~ *Set cement plug 4.33-333 + Tag*
- 10). Spot 10 sx plug at surface.
- 11). Cut off wellhead. Install dry hole marker. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>Monte C. Duncan</u>	TITLE <u>ENGINEER'S ASSISTANT</u>	DATE <u>10/21/92</u>
TYPE OR PRINT NAME <u>MONTE C. DUNCAN</u>		TELEPHONE NO. <u>393-7191</u>

(This space for State Use)

Orig. Signed by Paul Rauts

APPROVED BY _____ TITLE _____ DATE OCT 22 '92

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE WELL TO BE APPROVED