

RE MEMPHIS CIVIL DEFENDANCE COMMISSION
FEB 27 1966

FD-302 (Rev. 5-1-57)

1. The first step in the process of identifying a problem is to recognize that a problem exists. This is often done by comparing current performance with a desired state or goal. If there is a significant difference, a problem is identified.

Schizothorax

SOUTHERN NEW MEXICO OIL CORP.			Lease		Lease Book Entry		Well No.	
Oil Meter	Section	Township	Range	County				
M	10	10 SOUTH	32 EAST	LEA				
General Remarks Location of Well:								
600 feet from the SOUTH line and 600 feet from the WEST line								
Surface Level Elev.	Producing Formation		Pool		Estimated Age of Gas			
5536-1	SILVER		LUCK (SILVER)		100			

1. Is the Operator the only owner in the dedicated acreage outlined on the plat below? YES X NO ____ ("Owner" means the person who has the right to drill into and to produce from any pool and to appropriate the production either for himself or for himself and another. (65-3-29 (c) N.G.S.A. 1953 Comp.)
2. If the answer to question one is "No," have the interests of all the owners been consolidated by communication agreement or otherwise? YES ____ NO ____ . If answer is "yes," Type of Consolidation _____
3. If the answer to question two is "no," list all the owners and their respective interests below:

Order	Load Description	Value

9207103

CERTIFICATION

I hereby certify that the information in SECTION A above is true and complete to the best of my knowledge and belief.

Jas W West

AGENT

Company SALAMIN N.M. OIL CORP.

12-5-1963

I hereby certify that the well location shown on the plat is SECTION 8 was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief.

Once Submitted

12-3-1963

Registered Professional Engineer
and Licensed Surveyor, 1934: 12 1 1937

John W. Foster

[illegible]