

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-025-20282

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-1301

7. Lease Name or Unit Agreement Name:

Central Vacuum Unit

8. Well No.

109

9. Pool name or Wildcat Vacuum,
Grayburg, San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Texaco Exploration & Production, Inc.

3. Address of Operator

P. O. Box 3109, Midland, TX 79702

4. Well Location

Unit Letter I : 2310 feet from the South line and 660 feet from the East line

Section 6 Township 18S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- Set 3 1/2" CIBP @ 4380' (Grayburg-San Andres) Spot 20 Sx plug 4380'-4100' WOC Tag
- Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL
- Spot 30 Sx plug 3800'-3400' (Queen)
- Spot 20 Sx plug 2800'-2600' (Yates, Base-Salt)
- Spot 30 Sx plug 1600'-1200' (7 5/8" shoe, T-Salt) WOC Tag
- 10 Sx surf, Install dry hole marker.

THE COMPLETION MUST BE NOTIFIED
BY THE OPERATOR TO THE NEAREST
DISTRICT OFFICE AND THE COMPLETION
MUST BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

James T. Corbett

TITLE

FACILITY ENGINEER

DATE

4/2/01

Type or print name

JAMES T. CORBETT

Telephone No.

915-688-4436

(This space for State use)

APPROVED BY

TITLE

DATE

Conditions of approval, if any:

JC

dr

PLUGGING & ABANDONMENT WORKSHEET

(3 STRING CSNG)

OPERATOR TEVACO EXPLORATION & PRODUCTION
LEASENAME CENTRAL VACUUM UNIT

WELL # 109
SECT 6 TWN 18 S RNG 35 E
FROM 2310 N5L 660 EWL
TD: 4720 FORMATION @ TD GRAYBURG
PBDT: 4690 FORMATION @ PBDT SAN ANDRES

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	7 5/8	1552	SURF	CIRC
INTMED 1	3 1/2	4720	2000	CALC
INTMED 2				
PROD				
	SIZE	TOP	BOT	TOC DETERMINED BY
LINER 1				
LINER 2				
	CUT & PULL @		TOP - BOTTOM	
INTMED 1			PERFS	4381 - 4668
INTMED 2			OPENHOLE	-
PROD				

* REQUIRED PLUGS DISTRICT I

RUTLER (ANHYD)	
YATES	
QUEEN	
GRAYBURG	
SAN ANDRES	
CAPTAN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BRUSHY CANYON	
BONE SPRING	
GLORIETA	
BLINEBRY	
TUBB	
DRINKARD	
ABO	
WC	
PENN	
STRAWN	
ATOKA	
MORROW	
MISS	
DEVONIAN	

PLUG	TYPE	SACKS	DEPTH
PLUG	PLUG	CMNT	
EXAMPLES			
PLUG #1	OH	25 SXS	9850'
PLUG #2	SHOE	50 SXS	8700'-8800'
PLUG #3	CIBP/35'		5300'
PLUG #3	CIBP	25 SXS	5300'
PLUG #4	STUB	50 SXS	4600'-4700'
PLUG #6	RETNR SQZ	200 SXS	400
PLUG #7	SURF	10 SXS	0-10'
PLUG #1	CIBP	20 SX	4380-4100
PLUG #2	QUEEN	30 SX	3800-3400
PLUG #3	B-SALT	20 SX	2800-2600
PLUG #4	7 5/8 S	30 SX	1600-1200
PLUG #5	SURF	10 SX	10' - SURF
PLUG #6			
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #			
PLUG #			

7 5/8
@ 1552
TOC SURF
8 1/2
PERFED & CIRC
315 SX TO SURF

3 1/2
@ 4720
TOC 2000

TD 4720