

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instruction
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ P&A	5. LEASE DESIGNATION AND SERIAL NO. NM-0309375
2. NAME OF OPERATOR Shell Oil Company (Western Division)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME -
3. ADDRESS OF OPERATOR P.O. Box 1500, Midland, Texas 79701	7. UNIT AGREEMENT NAME -
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FSL & 660' FEL (SE/4 SE/4) Section 30, T-19-S, R-32-E, NMPM, Lea County, New Mexico	8. FARM OR LEASE NAME Middleton A Federal
14. PERMIT NO. -	9. WELL NO. 2
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3568' DF	10. FIELD AND POOL, OR WILDCAT Lusk (Strawn)
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30, T-19-S, R-32-E, NMPM
	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☒	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) _____	(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pull rods pump & tubing.
2. Run tbg & spot 25 sacks cement plug @ PBTD 11,264' and extending across perforations at 11,204' thru 11,250'.
3. Pull tbg.
4. Cut 1 1/2" csg. @ free point & recover csg.
5. Run tbg. 50' inside 1 1/2" stub & spot 25 sacks cement plug extending across stub.
6. Spot 25 sacks plug @ 7160', & spot 25 sacks plug @ 5000'.
7. Spot 50 sacks plug @ 3800' & extending across 3 5/8" csg shoe @ 3703'.
8. Spot 10 sacks cement plug @ surface.
9. Erect prescribed marker
10. Abandon

18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed By N.W. Harrison
N. W. Harrison

TITLE Staff Exploitation Engineer DATE June 25, 1968

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

APPROVED
JUL 3 1968
A. R. BROWN
DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.