

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20494
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1080-2
7. Lease Name or Unit Agreement Name NEW MEXICO "M" STATE
8. Well No. 7
9. Pool name or Wildcat VACUUM DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Texaco Exploration and Production Inc.	
3. Address of Operator P. O. Box 730 Hobbs, NM 88240	
4. Well Location Unit Letter <u>F</u> : <u>1800</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>1</u> Township <u>18-S</u> Range <u>34-E</u> NMPM LEA	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4011' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	ABANDONED WOLFCAMP & GLORIETA AND
	OTHER: RECOMPLETED TO VACUUM DRINKARD <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/7/93 - 5/1/93

- MIRU, RAN GR TO 9926' IN WOLFCAMP STRING, SET CIBP @ 9895' & CAPPED W/ 35' CMT.
- RAN GR IN DRINKARD STRING TO 7800', TIH W/ SHOE TO 7930', JUNK IN HOLE @ 7931', NOTIFIED MR. SEXTON @ NMCD. SET CIBP @ 7930' & CAPPED W/ 35' CMT, NEW PBTD @ 7895'. TESTED CSG TO 300#, OK.
- IN GLORIETA STRING SET CIBP @ 6100', SET CIBP @ 5950' & CAPPED W/ 35' CMT.
- IN WOLFCAMP STRING SET CIBP @ 7400'.
- PERFD DRINKARD W/ 2 JSPF FR 7606'-7666'. (49 PERF FT - 98 HLES)
- SPTD 25 GALS 20% NEFE 7680'-7550', SET PKR @ 7346', ACIDIZED PERFS 7606'-7666' W/ 5000 GALS 20% NEFE. MAX P = 3855#, AIR = 5.5 BPM. SWABBD BACK LOAD.
- PERFD DRINKARD W/ 2 JSPF FR 7530'-7588' (52 PERF FT - 104 HLES)
- SET RBP @ 7597', SPTD 25 GALS 20% NEFE, SET PKR @ 7414', ACIDIZED PERFS 7530'-7588' W/ 5000 GALS 20% NEFE. MAX P = 4250#, AIR = 4.6 BPM, SWABBED BACK LOAD.
- TOH W/ PKR & RBP. PLACED WELL ON PRODUCTION.
OPT 5-25-93 20 BOPD, 6 BWPD, 30 MCFD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE ENGINEER'S ASSISTANT DATE 6-16-93
TYPE OR PRINT NAME MONTE C. DUNCAN TELEPHONE NO. 393-7191

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 17 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 17 1993

LIBRARY