

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Enel Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-20508
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1258-1

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name  New Mexico "AE" State
2. Name of Operator Texaco Exploration and Production Inc.	8. Well No. 17
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	9. Pool name or Wildcat Vacuum Abo Reef
4. Well Location Unit Letter J : 2240 Feet From The South Line and 1720 Feet From The East Line Section 11 Township 18-S Range 34-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3994' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notified NMOCD. MIRU w/P&A equipment. Starting date 10-14-91.
2. TIH w/shoe, cleanout to 8675', TOH w/workstring.
3. Set CIBP @ 8665', capped w/35' Class C cmt, TOC @ 8630'.
4. Ran free point on csg, free @ 2206'.
5. TIH /DP, circ hole w/mud, TOH laying down DP.
6. Set CIBP @ 5000', capped w/35' of Class C cmt, TOC @ 4965'.
7. Set CIBP @ 4100', capped w/35' of Class C cmt, TOC @ 4065'.
8. Set CIBP @ 3380', capped w/35' of Class C cmt, TOC @ 3345'.
9. Cut csg @ 2205', TOH w/csg, circ hole w/mud.
10. Spt 30 sxs Class C cmt from 2205' to 2105', tagged plug @ 2055'.
11. Spt 30 sxs Class C cmt from 1890' to 1790'.
12. Spt 30 sxs Class C cmt from 433' to 333'.
13. Spt 10 sxs Class C cmt from 37' to surface.
14. Cut off wellhead, installed dry hole marker, cleaned location. Completion date 10-23-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. C. Duncan TITLE Engineer's Assistant DATE 10-23-91

TYPE OR PRINT NAME M. C. Duncan TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY Lyle F. Turpen TITLE OIL & GAS INSPECTOR DATE JAN 27 '92

CONDITIONS OF APPROVAL, IF ANY: