

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1600 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002520514
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-1733

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name New Mexico "L" State
2. Name of Operator Texaco E&P, Inc.	8. Well No. 6
3. Address of Operator P. O. Box 3109 - Midland, TX 79702	9. Pool name or Wildcat Vacuum Drinkard <i>Gloneta & Vacuum Wolfcamp</i>
4. Well Location Unit Letter <u>B</u> : <u>770</u> Feet From The <u>North</u> Line and <u>2090</u> Feet From The <u>East</u> Line Section <u>1</u> Township <u>18S</u> Range <u>34E</u> NMPM Lea County	

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4005 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 5-5-95 - Notified state authorities on intent to plug.

X 5-8-95 Cap CICR @ 5840' w/10 sx cmt Cal. TOC 5429'
X 5-8-95 Spot 10 SX cmt 5000', tag next day 4599'.
X 5-9-95 Spot 20 sx cmt 4300', Cal TOC @ 3488'.
X 5-9-95 Spot 10 sx cmt 2800', Cal TOC @ 2394'.
X 5-9-95 Spot 20 sx cmt 1700', Cal TOC @ 888'.
X 5-9-95 Spot 20 sx cmt 400' to 0'
Y 5-11-95 Locate hole in 2-7/8" 6100' +/-, sqz 150 sx cmt. Displace TOC to 3000', tag next day 3850'.
Y 5-11-95 Spot 10 sx cmt 2800', displace TOC to 2394'.
Y 5-11-95 Spot 20 sx cmt 1700', displace TOC to 888'.
Y 5-11-95 Spot 10 sx cmt 400' - 0'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James Calder TITLE P&A Supervisor DATE 5-11-95
TYPE OR PRINT NAME James Calder TELEPHONE NO. 915/335-5080

(This space for State Use)

APPROVED BY Carmy W. Hill TITLE OIL & GAS INSPECTOR DATE 5-11-95
CONDITIONS OF APPROVAL, IF ANY: