

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION
RULES AND REGULATIONS

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUN 30 10 40 AM '69

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-7653
7. Unit Agreement Name
8. Farm or Lease Name State AN
9. Well No. 10
10. Field and Pool, or Wildcat Vacuum
12. County Lee

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Salt Water Disposal
2. Name of Operator Getty Oil Company
3. Address of Operator Box 249, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER P , 990 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 18S RANGE 35E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mixed 25 sacks reg. cement and displaced to below packer with final pressure 1000#. 24 hr. SITP 450#. Mixed 50 sacks regular cement, spotted across perforations. Tagged top of cement plug in 5-1/8" casing at 4705'. Tested with 500# for 30 minutes, OK. Shot 5-1/8" casing at 3802', 3740', 3500', & 3290', could not pull. Shot at 2510, 2270, 2175 and could not pull. Shot at 2140' and pulled. Shot and recovered 250' of 8-5/8" casing. Set 25 sack plug across 5-1/8" stub 2300-2123', 35 sack plug across 8-5/8" stub 250' to 286'. Laid 10 sack cement plug in top of hole and installed dry hole marker. Location has been cleaned up and is ready for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY:

SIGNED C. L. Wade TITLE Area Supt. DATE 6-27-69

APPROVED BY John W. Runyan TITLE Geologist DATE SEP 24 1969

CONDITIONS OF APPROVAL, IF ANY: